



Ship Loading

Community Forum May 2009



Ship Loading

- Procedure for Loading of Ships
- Loading Screen
- Shed Recovery



Procedure for Loading Ships

- Stop Loading when Winds exceed 22 knots
- Stop Loading when Load Out Rate is less than 800 tph.



Loading Screen

Not so
successful.



Safer. Cleaner. Better.

